

Superfund Enterprise Management System Archived Site Inventory (SEMSARCH)

[MAP ID# 1](#)

Distance from Property: 0 mi. (0 ft.) X

Elevation: 5 ft. (Equal to TP)

FACILITY INFORMATION

EPA ID#: TXD990757627

SITE ID#: 0603561

NAME: ARCO POLYMERS INC - PT ARTHUR PLANT

ADDRESS: TEXAS FM 823 AND HWY 73

PORT ARTHUR, TX 77640

COUNTY: JEFFERSON

FEDERAL FACILITY: NOT A FEDERAL FACILITY

NPL: NOT ON THE NPL

NON NPL STATUS: NFRAP-SITE DOES NOT QUALIFY FOR THE NPL BASED ON EXISTING INFORMATION

SEMS SEARCH: [CLICK HERE](#)

Below information was gathered from the prior NFRAP update completed in 10/2013 update:

<u>ACTION</u>	<u>START DATE</u>	<u>COMPLETION DATE</u>	<u>RESPONSIBILITY</u>
PA - PRELIMINARY ASSESSMENT	9/1/1980	9/1/1980	EPA FUND
DS - DISCOVERY	NOT REPORTED	11/1/1979	EPA FUND
VS - ARCHIVE SITE	NOT REPORTED	9/1/1980	EPA IN-HOUSE

ACTION DESCRIPTIONS

PA - (PRELIMINARY ASSESSMENT) - COLLECTION OF DIVERSE EXISTING INFORMATION ABOUT THE SOURCE AND NATURE OF THE SITE HAZARD. IT IS EPA POLICY TO COMPLETE THE PRELIMINARY ASSESSMENT WITHIN ONE YEAR OF SITE DISCOVERY.

DS - (DISCOVERY) - THE PROCESS BY WHICH A POTENTIAL HAZARDOUS WASTE SITE IS BROUGHT TO THE ATTENTION OF THE EPA. THE PROCESS CAN OCCUR THROUGH THE USE OF SEVERAL MECHANISMS SUCH AS A PHONE CALL OR REFERRAL BY ANOTHER GOVERNMENT AGENCY.

VS - (ARCHIVE SITE) - THE DECISION IS MADE THAT NO FURTHER ACTIVITY IS PLANNED AT THE SITE.

[Back to Report Summary](#)